ASBESTOS INSPECTION REPORT

Rath Pump Rooms
Behind Rath Administration
Alley behind Veridian Credit Union

SUBMITTED TO:

City of Waterloo 714 Mulberry St. Waterloo, Iowa 50703

ASBESTOS INSPECTION

prepared by:

Travis J. Haas, Inspector

12/12/2007 Date

> 07-2735 I Inspector #

2/9/2008 License Expiration date

ADVANCED Environmental Testing and Abatement

803 Ricker Street Waterloo, Iowa 50703

REPORT DATA

BUILDING NAME:

Old Pump Rooms

INSPECTION AREAS: Interior & Exterior of Building

CLIENT CONTRACT:

City Waterloo 715 Mulberry St. Waterloo, Iowa Att: Chris Western

OVERVIEW:

A complete asbestos inspection was conducted by Travis J. Haas, Inspector (IA License # 07-2735I) on 12/7/07. The inspection was on the entire building located at 620 Iowa St., Dubuque, Iowa. There were a total of 9 samples taken from the interior and exterior of the buildings.

The purpose of this inspection was to identify asbestos containing materials prior to commencing an upcoming demolition. The inspection entailed a visual assessment of the property for suspect asbestos containing materials, collection, and submittal of bulk samples for analysis.

This report is a summary of the materials assumed to contain asbestos & samples confirmed to contain > 1% asbestos, their quantities, and locations.

Any sample under 10% asbestos can be point counted for a more accurate result.

SEE NEXT PAGE

SHIMMARY OF MATERIALS FOLIND TO CONTAIN ASBESTOS (Includes materials assumed to contain asbestos)

SUMMARY OF MAIR	SUMMARY OF MAIERIALS FOUND 10 CONTAIN ASBESTOS (Includes materials assumed to contain aspestos) ### McDonald's ### 620, lowa St. Dubuque, lowa 52001	(includes materials a	ssumed to contain as	spesios)	
TYPE OF MATERIAL	LOCATION	QUANTITY	% ASBESTOS	F or NF Damage	<u>Damage</u>
Caulking	East building around S.E. door	5 Sq. Ft	2%	본	9
Tar	Black tar on green roll roofing east building	10 Sq. Ft.	10%	Ä	on O
Tar	Black/grey tar on roof edges	10 Sq. Ft.	10%	ĸ	2
Glazina	Window Glazing	2 Windows	2%	¥	00
Tar	Black tar on penetrations West Building	10 Sq. Ft.	2%	Ą	ou
Electrical Blocks	Electrical Blocks in Electrical panel	5 Sq. Ft.	10%	Ą	2
Glazing	Window Glazing	1 Window	2%	Ľ	2

Advanced Technologies 803 Ricker St Waterloo, Iowa 50703

			Facility Name/Site Location	
			Rath Buildings Two Pump Rooms	Inspected By:
Lab NO	Sample No	Material	Material Description, Color, Location	Results
			East Building	
	R-1	Insulation	Insulation on pipe in crawl space.	%0
	R-2	Caulking	Caulking around S.E. door	5%
	R-3	Roll Roofing		%0
	R-4	Tar	Black tar on green roll roofing.	10%
	R-5	Tar	Black/Grey tar on roof edges	10%
	R-6	Glazing	Window glazing	2%
			West Building	
	R-7	Tar	Black tar on penetrations	5%
	R-8	Block	Electrical block in electrical panel.	10%
	R-9	Glazing	Window glazing	2%

EMC LABS, INC.

Laboratory Report 0060027

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044 Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:

ADVANCED ENVIRONMENTAL

Address:

TESTING & ABATEMENT, INC. 803

RICKER ST.

WATERLOO IA 50703

Collected:

Project Name/ **RATH PUMP BLDGS**

Address:

Job# / P.O. #:

Q15332

Date Received:

12/10/2007

Date Analyzed:

12/12/2007

Date Reported:

12/12/2007 .

EPA Method:

EPA 600/M4-82-020

Submitted By: Collected By:

Customer

TRAVIS HAAS

Lab ID	Sample	Layer Name /	Asbestos Asbestos		Т	N A -L4	
Client ID	Location	Sample Description	Aspestos Detected	Asbestos Type (%)		Non-Asbestos Constituents	
0060027-001 R-1	EAST BLDG-IN CRAWLSPACE	Insulation, Brown	No			Cellulose Fiber	95%
						Quartz Binder/Filler	5%
0060027-002 R-2	EAST BLDG- AROUND S. DOOR	Caulking, White	Yes	Chrysotile	5%		
						Carbonates	
						Quartz	0.507
						Binder/Filler	95%
0060027-003 R-3	EAST BLDG-ON ROOF HATCH	Rolled Roofing, Green/ Black	No			Cellulose Fiber	20%
						Quartz	
						Carbonates	
						Binder/Filler	80%
0060027-004 R-4	EAST BLDG-ON GREEN ROLL ROOFING	Tar, Black	Yes	Chrysotile	10%		
						Carbonates Binder/Filler	90%
0060027-005 R-5	EAST BLDG-ON ROOF EDGES	Tar, Black	Yes	Chrysotile	10%		
						Carbonates	
						Binder/Filler	90%
0060027 - 006 R-6	EAST BLDG- WINDOW	Glazing, Red	Yes	Chrysotile	2%	Cellulose Fiber	<1%
						Carbonates	
						Quartz	
						Binder/Filler	97%
0060027-007 R-7	WEST BLDG-ON PENETRATIONS	Tar, Black	Yes	Chrysotile	5%		
						Carbonates	
						Quartz	0.507
						Binder/Filler	95%

EMC LABS, INC.

Laboratory Report 0060027

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044 Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:

ADVANCED ENVIRONMENTAL

Address:

TESTING & ABATEMENT, INC. 803

RICKER ST.

WATERLOO IA 50703

Collected:

Address:

Project Name/

RATH PUMP BLDGS

Job# / P.O. #:

Date Received:

12/10/2007

Q15332

Date Analyzed:

Date Reported:

12/12/2007 12/12/2007

EPA Method: Submitted By: EPA 600/M4-82-020 TRAVIS HAAS

Collected By:

Customer

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)		Non-Asbestos Constituents	
0060027-008 R-8	WEST BLDG-IN ELECTRICAL PANEL	Block, Brown	Yes	Chrysotile	10%		
						Quartz Gypsum Binder/Filler	90%
0060027-009 R-9	WEST BLDG- WINDOW	Glazing, Red/ Off White	Yes	Chrysotile	2%		
						Carbonates	

Analyst - Johann Hofer

Signatory - Lab Director - Kurt Kettler

Quartz Binder/Filler

98%

INTRODUCTION

For each area of the building, the inspector performing the inspection did the following:

- 1. Visually inspected the area(s) to identify the locations of all suspect Asbestos Containing Building Materials.
- 2. Identify all homogeneous areas of friable and non-friable suspected asbestos.
- 3. Assume, if necessary, that some or all of the homogeneous area(s) are Asbestos Containing Material (ACM), and for each homogeneous area that is not assumed to be ACM, collect and submit bulk samples for analysis.

DEFINITIONS:

HOMOGENEOUS AREA

An area which appears similar throughout in terms of color, texture, and date of material application.

SURFACING MATERIAL

Material in a building that is sprayed-on, troweled-on, or otherwise applied to surfaces, such as acoustical plaster on ceilings and fireproofing materials on structural members, or other materials on surfaces for acoustical, fireproofing, or other purposes.

THERMAL SYSTEM INSULATION

Means material applied to pipes, fittings, boilers breeching, tanks ducts, or other interior structural components to prevent heat loss or gain, or water condensation, or other purposes.

MISCELLANEOUS MATERIAL

Interior building material on structural components, structural members or fixtures, such as floor and ceiling tiles, and does not include surfacing material or thermal system insulation.

SAMPLING AND ANALYSIS

All samples to be analyzed by Polarized Light Microscopy (PLM). Analysis was performed in accordance with EPA 40 CFR, Part 763, Appendix A to Subpart F.

A homogeneous area was considered not to contain Asbestos Containing Material (ACM) only if the results of all samples collected from the area showed asbestos in the amounts of one (I) percent (%) or less (_1%). A homogeneous area contains ACM when one or more samples collected from that area shows greater than one (1) percent (%) asbestos (>1%).

FRIARI F

Any material containing more than one (1) percent (%) asbestos, that, when dry can be crumbled, pulverized, or reduced to a powder by hand pressure.

NON-FRIABLE (CATEGORY I)

Asbestos Containing packings, gaskets, resilient floor covering, and asphalt roofing products, containing more than one (1) percent (%) asbestos.

NON-FRIABLE (CATEGORY II)

Any excluding Non-Friable (Category I) Asbestos Containing Material, containing more than one (1) percent (%) asbestos.