



Car Seat Recalls/Defects & Safety Notices - Revised 6/21/2017

This list, covers child car seats manufactured after 12/31/08, was compiled by the Safety Restraint Coalition (425) 828-8975 or 1-800-282-5587. For older seats see separate Archive List (revised yearly). Information may change; always call manufacturer to verify. **Most recent addition(s) are shaded.**

This information may not be posted on a website or included in blogs without the express written permission of the Washington State Safety Restraint Coalition 425-828-8975.

4moms

888-614-6667 www.4moms.com

Infant Seat

Self-installing Car Seat Made 7/1/16 - 10/31/16. Problem: Hooks locking carrier to base may stick or fail to attach. Until replaced, double check proper locking into base by pulling up on carrier handle to assure it's secure or install carrier without base. Locate serial number then visit www.4moms.com/recalls or call: 888-614-6667 for replacement carrier.

Aidia, Inc. (No Recalls)

866-328-8661 www.aidiaproducts.com

Angel Guard (No Recalls)

800-815-6330 www.angel-guard.com

Aprica (No Recalls)

888-569-7288 www.urbinibaby.com

Aria Child (No Recalls)

888-569-7288 www.apricacom

Baby Jogger, LLC

800-241-1848 www.babyjogger.com

Infant Seats

City GO Infant seat Models BJ64510, BJ64529; City GO Infant Car Seat Base Models BJ80400, BJ61500; City Mini Car Seat/Stroller System Model BJ72510; Vue Lite Car Seat/Stroller System BJ70411, BJ70424, BJ70431 made 11/3/14 - 4/30/15. **Problem:** Incorrect/missing information on labels/instruction book may decrease correct use of seat increasing risk of injury. **Call:** 800-241-1848 for free replacement infant car seat.

Baby Trend

800-328-7363, www.babytrend.com

Harnessed Booster

3-in-One Hybrid LX model FB48417 made 7/14/16 sold only at Wal-Mart & model **FB58181** made 7/23/16 sold only at Military Exchanges. **Problem:** In a crash, center adjuster may detach in harnessed mode if child weighs more than 40 pounds. Locate serial number then visit www.babytrend.com or call: 800-328-7363 to determine if your seat requires free replacement.

3-in-One TrendZ Fastback Models FB60070, FB60408 made 10/11 - 7/13. **Problem:** Buckle may become difficult to unlatch or become stuck in latched position. **Call:** 800-328-7363 for new buckle. Effectiveness of buckle to restrain child is NOT affected.

Bergeron (No Recalls)

800-371-2778 www.adaptivemall.com

Britax

888-427-4829 www.britaxusa.com

Infant Seats

Problem #1: B-Safe 35 Models

E1A183F, E1A185M, E1A185P, E1A186R, E1A203F, E1A205M, E1A205P, E1A206X, E1A206Z, E1A207E, E9LU65V, E9LU66X, E9LU66Z, E9LU67D, E9LU67E, EXA185M, S02063600, S02063700, S03803400, S03803500, S03803700, S03803800, S03803900, S04144400, S04144500, S04144600, S04145000, S04402800, S04884200, S04884300, S04975600, S04978900, S05260200, S06020300, S06020400, S06020500, S06020600, S06020700, S06020800, S06020900, S06147100, and S921800 **B-Safe 35 Elite Models** E1A215T, E1A215U, E1A216P, E1A221Q, E1A225C, E1A225U, E1A226L, E9LS51Q, E9LS56C, E9LS56L, E9LS57F, E9LS57G, E9LS57H, EXA216L, S01298600, S02063800, S02063900, S02064000, S04281200, S04281300, S04628500, S06018800, S06020000, S06020200, S923700 **BOB B-Safe 35 Models** E9LT34A, E9LT34C, E9LT35X, and EXLT34A. Made 11/1/15-5/31/17. Center tab on chest clip can break presenting choking hazard to infant. **Go to** www.bsaf35clip.com to have a remedy kit mailed or **Call:** 1-833-474-7016.

Problem #2: B-Safe 35 Model EX-LU65M and models beginning "E9L" U65M, U65P, U63F, U66R, S63F. **B-Safe 35 Elite Models** beginning "E9LS" 55T, 56P, 55U, 66C, 65U & **B-Safe Travel Systems Models** beginning "S91" 4900, 5400, 5200, and S921900, S01635200. Made 10/1/14 - 7/1/15. Car seat carry handle may crack/fracture while carrying it, causing risk of injury to child. Do not carry by handle until fixed. Recall does not affect seat when used in vehicle or on stroller. **Go to** www.bsaf-e35recall.com to order remedy kit and watch video or **Call:** 800-683-2045.

Chaperone Problem #1: Models begin "E9L692" J, K, L, & M made 9/1/10 - 4/30/11. Harness adjuster may detach from the shell. Should it detach the harness straps will not properly secure the child resulting in increased risk of injury in a crash. If the harness adjuster on your Chaperone Infant Car Seat detaches, discontinue use of the product immediately and contact Britax. **Call:** 888-427-4829 for a remedy kit including a harness adjuster clip & instructions

for properly installing it. **Problem #2: Models begin "E9L69" N9, P2, P3, & P5** made 4/09 - 5/10. Chest clip is brittle & may break causing sharp edges/choking hazard. **Call:** 888-427-4829 for instructions & new chest clip. If chest clip is broken, remove chest clip & any fragments. Continue to use seat until replacement chest clip is installed.

Convertible Seats

Advocate 70-G3, Boulevard 70-G3 and Pavillion 70-G3. Models begin "E9L" J91A, E91M, J91S, J92E, J93P, J93S, K91A, K31A, K31Q, K32D, K32Z, K33Q, L11A, L11Q, L12D, L12Z, G81A, G83N, G83P, G83X, G83Y, L21A, L23P, L23Y made 6/1/12 - 8/31/12. **Problem:** Child chewing on HUGS chest pad may bite off small piece, presenting choking hazard. **Call:** 888-427-4829 for new HUGS chest pads. New HUGS pads are marked "PP" under harness webbing.

Advocate ClickTight Models E9LT86F, E1A135Q, E9LT86G, E9LT85Q, E9LT86A, E9LT86H, E9LT85S, E1A015Q, E1A016A, and E1A016H. Made 8/1/14 - 7/29/15. **Problem:** Harness adjuster button (red) may remain down in release position and prevent harness from locking. Continue using seat if harness button does not stick and harness remains tensioned. All registered owners will receive a repair kit automatically. **Go to** www.BritaxClickTightConvertibleRecall.com to have a remedy kit mailed or **Call:** 1-888-427-4829, Option 3.

Boulevard ClickTight Models beginning "E1A" 013Q, 016A, 016H, 135Q, LT85Q, and beginning "E9LT" 85Q, 85S, 86A, 86F, 86G, 86H made 8/1/14 - 7/29/15. **Problem:** Harness adjuster button (red) may remain down in release position and prevent harness from locking. Continue using seat if harness button does not stick and harness remains tensioned. All registered owners will receive a repair kit automatically. **Go to** www.BritaxClickTightConvertibleRecall.com to have a remedy kit mailed or **Call:** 1-888-427-4829, Option 3.

Marathon ClickTight models E1A116L, E9LT76P, E9LT71Q, E9LT76N, E9LT76B, E9LT75R, E9LT76L, E1A006B, E1A005R and EXA116L made 8/1/14 - 7/29/15. **Problem:** Harness adjuster button (red) may remain down in release position and prevent harness from locking. Continue using seat if harness button does not stick and harness remains tensioned. All registered owners will receive a repair kit automatically. **Go to** www.BritaxClickTightConvertibleRecall.com to have a remedy kit mailed or **Call:** 1-888-427-4829, Option 3.

BubbleBum (No Recalls)

800-969-6586, www.bubblebum.us

CARES (No Recalls)

800-299-6249 www.kidsflysafe.com

Chicco

(No Recalls on seats less than 10 years old)

877-424-4226 www.chiccousa.com

CLEK Inc. (No Recalls)

866-656-2462 www.clekinc.com

Columbia Medical (No Recalls)

800-454-6612 www.columbiamedical.com

Combi USA, Inc.

800-992-6624 www.combiusa.com

Convertible Seats

Problem 1: Coccoro Model 8220 made 1/1/09-7/31/16. When installed forward-facing and secured with vehicle LAP-ONLY belt, excessive force may be transferred to the car seat occupant in a crash increasing their risk of injury. (Recall does not affect use of seat when installed in rear-facing position, or if installed forward-facing with lap/shoulder belt and lock-off or lower anchors and tether.) **Call:** 888-232-3294 or visit <http://registration.combiusa.com/recall> for free Remedy Kit with new bottom cover.

Problem #2:

- **Coccoro Model 818220** made 1/1/09 - 12/31/12
- **Zeus Turn Model 8815** made 7/15/07 - 3/31/09
- **Zeus 360** made 2/1/09 - 5/31/12.

Embedded plastic button prevents harness from meeting minimum breaking strength tolerance when tested independently from child restraint. Could affect overall performance of child restraint in event of crash. **Call:** 844-697-1690 for Remedy Kit with new straps or visit <http://www.combiusa.com/Safety-Notifications/Recall-Information.aspx> to register and receive Remedy Kit. Combi encourages use of seat until kit is received and installed.

Compass (See Tomy)

Convoid (No Recalls)

888-266-8243 www.convoid.com

Cosco (See Dorel)

Cybox

800-593-5522 www.regallager.com

Booster Seats

Cybox Solution X-fix Models 0500200 & 0500760 made 2/1/10 - 2/28/10. **Problem:** Seats are labeled with incorrect warning related to securing an unoccupied booster. Increases risk of unoccupied booster striking vehicle occupants causing injury in a severe crash. **Call:** 800-593-5522 or visit www.regallager.com/recall for a new warning label and Owner's Manual. *Safety of the seat when used with a properly secured child is not affected.* If the seat is unoccupied, ensure it is belted into the vehicle with the vehicle seat belt even when using the LATCH connectors.

Diono (No Recalls)

888-366-7909 www.diono.com

Dorel Juvenile Group (Cosco,

Eddie Bauer, Safety 1st, Maxi Cosi, Quinny)

800-544-1108 www.djgusa.com

Infant Seats

All Infant Seats sold as part of a stroller system under Safety 1st, Cosco, Disney, or Eddie Bauer. Made 1/6/08 - 4/6/09. Models, beginning "22-" were sold under the following names and numbers:

- Safety 1st Sojourn: 057 DBY, 085 DWA, 057 CLN, 057 HRT, 322 HRR, 322 PTK, 057 LPH, & 085 LYN.
- Safety 1st Eurostar: 322 KDL, 322 LXI, 322 OLY, 322 PRS, 322 MAI, & 325 COB.
- Safety 1st Explorer: 095 RBK.
- Safety 1st Lite Wave: 380 LGA & 380 MSA.
- Safety 1st Vector: 627 WAV & 325 PAC.
- Cosco Sprint: 300 FZN, 300 OSF, 300 CSF, 300 JJV, 300 THD, & 300 TWD.
- Disney Propack: 627 AWF, 355 LBF, 305 NAB, 305 PPH, & 355 PWK.
- Eddie Bauer Adventurer: 627 CGT, 627 FRK, 627 SNW & 627 WPR.
- Eddie Bauer Endeavor: 627 KGS & 655 BYTE.

Problem: Handle releases suddenly when carried. Seat may flip & child may fall. **Call:** 866-762-3316 or visit www.djgusa.com to order handle repair kit. Until installed, do not use handle to carry.

Comfy Carry Model IC123 FSM made 5/1/11 - 4/25/12. **Problem:** Some seats were sold without lower LATCH attachment strap. **Call:** 877-416-8111 for replacement base with LATCH. Until new base is received consumers should use the seat installed with a seat belt.

Maxi-Cosi Mico Models beginning "22-" 371CIP, 371CTR, 371FSB, 371LYP,

371MJR, 371PHT, 371RFR, 371TRL, & 372TTH made 5/1/08 - 4/30/09. **Problem:** Harness may gradually loosen during normal use increasing risk of injury in crash. Until repaired double check to assure harness is adjusted snugly around child. **Call:** 866-623-3139 or email consumer@djgusa.com for repair kit.

OnBoard Models beginning "22-" 077FSM, 078DMS, 346VAL, 356NTR, 356PRO, 356TRI, 657FRK, 657MTT, 657PST, 657SNW, 657SON, & 657VND also model IC-072SON made 5/1/08 - 4/30/09. **Problem:** Harness may gradually loosen during normal use increasing risk of injury in crash. Until repaired double check to assure harness is adjusted snugly around child. **Call:** 866-623-3139 or email consumer@djgusa.com for repair kit.

OnBoard 35 Model IC124 FSM made 5/1/11 - 4/25/12. **Problem:** Some seats were sold without lower LATCH attachment strap. **Call:** 877-416-8111 for replacement base with LATCH. Until new base is received consumers should use the seat installed with a seat belt.

Convertible Seats

Safety1st Complete Air LX Models CC050AJH, CC050ANY, CC050ANZ, CC050AOQ and Safety1st Complete Air SE Models CC051AIR made 7/20/10 - 5/18/11. **Problem:** Arrows for rear facing belt path installation may appear to point to forward facing belt path. If not installed properly, child may be injured in a crash. **Call:** 877-675-2355 or email rbbaselabel@djgusa.com for new label.

Safety1st Alpha Omega Elite Models 22187ANL, 22187REM, 22187REMA, 22187SAR, 22187SARA, 22465FSM, CC033BMT, CC043ANK, CC043ANL, CC043AQS made 7/20/10 - 5/18/11. **Problem:** Arrows for rear facing belt path installation may appear to point to forward facing belt path. If not installed properly, child may be injured in a crash. **Call:** 877-675-2355 or email rbbaselabel@djgusa.com for free new labels and installation instructions.

Alpha Omega, Alpha Omega Elite, Enspira, Maxi-Cosi Priori, Prospect, & Vantage Models beginning "22-" 148RDH, 149PAL, 150BNS, 152BVL, 152CMN, 152RGS, 154HTR, 155BDF, 155HMR, 155NSHE, 155OTC, 155TRP, 158BLL, 158GRS, 158SPA, 159SGT, 172BKE, 172BRT, 172OKW, 172PHO, 172SVT, 177SNP, 177SNP2, 178SCT, 178STL, 178VSS, 185BVL2, 188BVL2, 195SVS, 195SVS2, 412, 439ABY3, 439HTP3, 439OKP3, 439VNS3, 449GES, 452RBYE, 453BCT, 453FSM, 456BVL, 456CAB, 456CAO, 456CSR, 456LMT, 456MIL, 456MRR, 456NTM, 456NTR, 456PRO, 456SCY, 456SUZ, 456TRI, 456TTN, 458FTM, 458NYC, 459MTG, 462BLN, 465BMT, 469BSE, 469BSEC, 475BVL, 476CIP, 476CTR, 476FSB, 476GIP, 476ISP, 476NOW, 476NRF, 476PHT, 476PMK, 476PNG, 486CRI, 486GIP, 486TTH, 546BSE, 547CHA, 553BVL3, 554PCR, 554PCR3, 554RCR3, 561WAL, 564ARZ, 564MIL,

564NTR, 564OKW, 564PHO, 564PRO, 564TRI, 564VLC, 567GRH, 574PCR3, 580BYR, 740HPN, 741ATI, 741BWD, 741GRT, 741, 755BLD, 758BYT, 758CMP, 758FRK, 758HDS, 758HID, 758KGS, 758PST, 758SNW, 758SON, 758VND, 759MTT, 790CGT, 790SNW, 790WPR, 790WPR2, 799MER, 880BYT, 880MTT, 880MTTA, 880SON, 880SONA, & 560FSM also models 93-560FSM, 17-439ABY, & 17-439HTP made 5/1/08 - 4/30/09. **Problem:** Harness may gradually loosen during normal use increasing risk of injury in crash. Until repaired double check to assure harness is adjusted snugly around child. **Call:** 866-623-3139 or email consumer@djgusa.com for repair kit.

Eddie Bauer Deluxe 3 in 1 convertible Models beginning 22790CGT, CC046AAI, CC046AAU, CC046CTA, CC046SNW, CC046WPR made 7/20/10 - 5/18/11. **Problem:** Arrows for rear facing belt path installation may appear to point to forward facing belt path. If not installed properly, child may be injured in a crash. **Call:** 877-675-2355 or email rbbaselabel@djgusa.com for free new labels and installation instructions.

Downunder (No Recalls)

Dream On Me (No Recalls)

732-748-1300 www.dreamonme.com

Eddie Bauer (See Dorel)

Evenflo

800-233-5921 www.evenflo.com

Infant Seats

Embrace35 Models 30711365, 31511040, 31511323, 31511400, 3151198, 3151953, 31521138, 46811205, 46811237, 48111200, 48111215, 48111215A, 48111218, 48111234, 48111235, 48111235A, 48111462, 48411391, 48411391D, 48411392, 48411504, 48411504d, 52911307A, 52921040, 55311138, 55311238, and 55311292 made 12/1/11 - 5/31/13. **Problem:** Harness buckle may become stuck in latched position making it difficult to remove child. Order new buckle at www.buckle.evenflo.com or **Call:** 800-490-7591

First Choice Model 3604098 made 1/16/09 - 9/29/09. **Problem:** Mandatory information may be missing from product labels. **Call:** 800-233-5921 for replacement labels.

Convertible Seats

Buckle Recall on these models:

- **Momentum 65 (LX and DLX) Models beginning "385"** made 3/4/13 - 8/26/13.
- **Sure Ride DLX Models beginning with "371"** made 6/20/12 - 10/17/13.
- **Titan 65 Models beginning "371"** made 6/20/12 - 10/17/13.

Problem: Harness buckle may become

stuck in latched position making it difficult to remove child. Order new buckle at www.buckle.evenflo.com or **Call:** 800-490-7591

Harnessed Booster/All-in-1

Buckle Recall on these models;

- **Chase, Chase LX & Chase Select Models beginning "306"** made 8/23/11 - 3/3/14
- **Chase LX and DLX Models beginning "329"** made 8/23/11-3/3/14.
- **Secure Kid (LX, DLX, 100, 300, and 400 models) beginning "308"** made 12/13/11 - 3/3/14.
- **Symphony 65, 65E3 (LX and DLX) Models beginning "345" or "346"** made 10/2/12-8/26/13.
- **Maestro and Maestro Performance models beginning "310"** made 8/22/11 - 10/17/13 have buckle recall (below) and **Maestro Model numbers beginning "310"** made 11/24/09 - 4/9/10 have **Problem #2:** In a crash, crack may form at front of seat causing child not be properly restrained. **Call:** 800-233-5921 for reinforcement kit. Children weighing less than 40 lbs. should use another seat until repaired; those weighing more than 40 lbs. may continue use only as a booster until repaired.

Problem: Harness buckle may become stuck in latched position making it difficult to remove child. Order new buckle at www.buckle.evenflo.com or **Call:** 800-490-7591

Evolve 3-in-1 Combination

Booster Models 34411700 and 344117421 made before 2/9/16 when used with harness. **Problem:** Child may reach button and loosen harness. IF child loosens harness stop using seat until remedy kit is installed. **Order** remedy kit at www.evolve.evenflo.com or **Call:** 800-233-5921

Transitions 3-in-1 Combination

Booster Models 34411686, 34411695, and 34411029, made 12/18/14 - 1/29/16 when used with harness. **Problem:** Child may reach button loosening harness and increasing risk of injury in crash. **Order** remedy kit at www.transitions.evenflo.com or **Call:** 800-233-5921

Booster Seats

Big Kid Model 30911173AD, 3091967AD, 30911118AD & 30911120D.

Problem: Small number of seats intended for display were incorrectly shipped to institutional customers. Seats were shipped between 8/6/12 - 9/18/12 and meet all crashworthiness standards. Affected units have a label stating: "Display Only, "Not intended for sale" on back of headrest. **Call:** 800-233-5921 for instruction manual, registration card & label.

Exo Motion

(See Recaro)

E-Z-On Products (No Recalls)

800-323-6598, www.ezonpro.com

First Years (See Tomy)

Fisher Price (See Britax)

GoBooster (No Recalls)

888-327-4336 http://gobooster.com

Goodbaby USA (No Recalls)

844-543-2020 www.gbchildusa.com

Graco

800-345-4109, www.gracobaby.com

Infant Seats

Graco Buckle Recall on:

- **SnugRide & SnugRide Classic Connect** made 3/1/11 - 5/31/13
- **SnugRide 30 & SnugRide Classic Connect 30** made 7/1/10 - 1/31/13;
- **SnugRide 35 & SnugRide Classic Connect 35** made 5/1/11 - 1/31/13
- **SnugRide Click Connect 40** made 6/1/12 - 12/31/12
- **Aprica A30** made 7/1/11 - 4/30/12.

Problem: Some harness buckles can become stuck in latched position. Effectiveness of buckle to restrain child is NOT affected. **Order replacement buckle** online www.GracoBuckleRecall.com or **Call:** 877-766-7470.

Convertible Seats

Buckle Recall on these models

- **Classic Ride 50** made 10/1/11 - 9/30/13.
- **Cozy Cline, Toddler SafeSeat-Step 2** made 1/1/06 - 4/30/10.
- **My Ride 70** made 5/1/12 - 7/31/13.
- **My Size 70, Size4Me 70, Headwise 70, Headwise 70 withSafety Surround** made 1/1/12 - 7/31/13 (and 8/3/13 as some made after the end date of production were made with the old buckles).
- **Ready Ride 70** made 10/01/10 - 9/30/13.
- **Smart Seat, Smart Seat with Safety Surround** made 12/1/10 - 9/30/13 and 10/9/13, 12/25/13, 1/10/14 (some made after the end date of production were made with the old buckles).

Problem: Some harness buckles can become stuck in latched position. Effectiveness of buckle to restrain child is NOT affected. **Order**

replacement buckle online www.GracoBuckleRecall.com or **Call:** 877-766-7470.

Classic Ride model 1812930 made 3/1/14 - 2/28/15. **Problem:** Label missing information on locating instructions. **Order replacement label** https://pages.email.gracobaby.com/2016LabelRecall/ or **Call:** 800-345-4109.

Comfort Sport models 1794333, 1813040 made 3/1/14 - 2/28/15. **Problem:** Label is missing information on location of instruction book. **Order free replacement label** at https://pages.email.gracobaby.com/2016LabelRecall/ or **Call:** 800-345-4109.

Extend2Fit model 1954477 made 11/27/15 - 1/20/16. **Problem:** Recline label affixed to wrong location may result in infant too upright or toddler too reclined. Assure all labels including recline label identifying recline positions 1-6 on each side of seat are not in same language. **Call:** 800-345-4109 for new label.

My Ride 65, My Ride 65 with Safety Surround made 4/1/09 - 7/31/13 and 9/30/13. **Problem #1:** Some harness buckles can become stuck in latched position. Effectiveness of buckle to restrain child is NOT affected. **Order replacement buckle** online www.GracoBuckleRecall.com or **Call:** 877-766-7470. **Problem #2: My Ride 65.** In addition to model numbers & dates listed, **fabric tag on back of harness MUST be labeled 2014/06.**

- Model 1908152 made 7/23/14 - 7/27/14
- Model 1813074 made 6/20/14 - 7/27/14
- Model 1872691 made 5/16/14 - 8/1/14
- Model 1853478 made 7/11/14 - 7/27/14
- Model 1871689 made 7/5/14 - 7/24/14
- Model 1877535 made 5/26/14 - 7/27/14
- Model 1813015 made 7/3/14 - 7/24/14
- Model 1794334 made 5/20/14 - 7/15/14

Problem: Harness webbing does not meet breaking strength. **Order** new harness webbing kit at Gracobaby.com or **Call** 800-345-4109 Seat may continue to be used while waiting for replacement kit.

Ready Ride Models 1924519, 1923520 made 3/1/14 - 2/28/15. **Problem:** Label is missing information on instruction book location. **Call:** 800-345-4109.

All-in-1

Milestone Models 1910130, 1923980, 1926538, 1926539 made 7/9/15 - 10/9/15. **Problem:** Labels do not have required wording about how to install seat with LATCH or seat belt per FMVSS 213. Recall does not affect safety performance. Registered owners will be sent a new label or **Call:** 800-345-4109.

Combination Seats

Buckle Recall on these models:

- **Argos 70 and Argos 70 Elite** made 5/1/11-7/31/13.
- **Nautilus 3-in-1, Nautilus Elite, Nautilus Plus,** made 10/1/27-7/31/13 (and 8/19/13 as some seats were made using recalled buckles).

Problem: Harness buckle can become stuck in latched position. Effectiveness of buckle to restrain child is NOT affected. **Order replacement buckle** using Graco's online order form at GracoBuckleRecall.com or **Call:** 877-766-7470.

Booster Seats

Turbo booster seat models:

- **1963973** made 3/8/16-4/2/16
- **1963974** made 12/22/15-3/30/16
- **1963975** made 12/22/15-3/17/16
- **1963976** made 2/17/16-3/24/16
- **1967886** made 1/13/16-4/5/16
- **1975173** made 3/29/16

Problem: Owner's manual omits instruction to prevent seat from becoming projectile by buckling it when not in use. Seat is still effective to restrain child. Verify your booster is affected then **download** the information online at https://pages.emailgracobaby.com/2016TurboBoosterRecall/ or **Call:** 800-345-4109 for missing instructions.

Harmony (No Recalls) 877-306-1001

www.harmonyjuvenile.com

Hauk Fun for Kids (No Recalls)

905-455-5888

Immi (See Safe Guard)

JJ Cole (See Tomy)

Jané (No Recalls)

415-824-12371 www.jane.com

Jeffco Fibres (No Recalls)

508-673-1001 www.jeffcofibres.com

Jupiter Industries (No Recalls)

800-465-5795 www.jupiterindustries.com

Kiddy

678-377-3309 www.kiddyusa.com

Combination Seats

World Plus Combination seat model 51-100WP made 2/1/12 - 10/5/13 (all models ever produced).

Problem: Buckle tongue on shield may not fully engage leaving child unrestrained. Affects seat only when used with shield (not as booster). **Call:** Kiddy Customer Service 855-925-4339 to arrange return of seat and reimbursement of full purchase price.

Kids Embrace (No Recalls)

866-947-3287 www.kidsembrace.com

Lamaze (See Tomy)

LaRoche Brothers (No Recalls)

(See Jeffco Fibres)

Learning Curve (See Tomy)

Lenox Juvenile Group

(No Recalls) (Out of business)

Lil Fan (No Recalls)

317-804-9160 www.lilfan.com

Little Tikes (No Recalls)

800-321-0183 www.littletikes.com

Maxi-Cosi (See Dorel)

Merritt Manufacturing

317-409-0148 www.eztether.com

Mia Moda, Inc.

866-642-6632 www.miamodainc.com

Infant Seats

Mia Moda Viva and Viva Supreme Model 5000, 5001, 5050, 5051, 5070, 5071, 5080, & 5081. **Problem:** Harness splitter plate on rear of seat has sharp edges & may cut harness or base may crack in crash. In crash child would not be properly restrained. **Call:** 877-546-8437 Immediately stop using the seat. Manufacturer will offer refund.

Nania (See Team-Tex)

Nuna (No Recalls)

855-686-2872 www.nuna.eu/USA/index

Orbit Baby

877-672-2229, www.orbitbaby.com

Infant Seat

Orbit Baby Car Seat Bases

Problem: G2 Bases model ORB822000 with Batch #A0840, A0860 or A0880 made 3/20/13 - 7/20/13. StrongArm knob may detach or spin without tightening base preventing proper installation. Register seat at Orbit website, then **Call:** 877-672-2220 for StrongArm knob repair kit. If seat is not tightly secured then install without base until repaired.

Peg Perego (No Recalls)

800-671-1701 www.pegperego.com

Phil & Teds (No Recalls)

800-839-4985 www.philandteds.com

Porsche (Contact Britax)

Recaro

888-973-2276 www.recaro.com

Convertible Seats

Como all models made 11/1/07 - 2/16/09. **Problem:** Harness may not tighten/lock properly. In crash child may not be securely restrained & sustain injury. **Inspect seat:** Take empty seat & pull on harness adjuster strap to fully tighten harness. Next, pull on

both shoulder straps without lifting/pressing harness release lever. If straps loosen, immediately stop using seat. **Call:** 888-473-2290 for replacement. If harness straps stay tight continue using seat.

ProRide All models beginning with 332.01 made 4/9/10 - 6/9/15 **Problem:** Tether may detach from car seat during crash increasing risk of injury to child/other occupants. Email recarorecall@m-s-s.com or **Call:** 866-628-4750.

PerformanceRide All models beginning with 33301 made 1/15/13 - 6/9/15. **Problem:** Tether may detach from car seat during crash increasing risk of injury to child or other occupants. **Call:** 866-628-4750 or email recarorecall@m-s-s.com.

Signo Problem: All models made 11/1/07 - 2/16/09. **Problem:** Harness may not tighten/lock properly. In crash child may not be securely restrained & sustain injury. **Inspect seat:** Take empty seat & pull on harness adjuster strap to fully tighten harness. Next, pull on both shoulder straps without lifting/pressing harness release lever. If straps loosen, immediately stop using seat. **Call:** 888-473-2290 for replacement. If harness straps stay tight continue using seat.

Regal Lager (See Cybex)

Safe Traffic System

(No Recalls) 847-233-0365
www.safetrafficsystem.com

SafeGuard (No Recalls)

800-586-7839 www.safeguardseat.com

Safeline Kids (See Tripleplay)

Safety Angel/Safe Start

(No Recalls)
561-732-1233 www.safetyangel.com

Safety Baby (see Team Tex)

Safety 1st (see Dorel)

Sammons Preston (No Recalls)

800-323-5547
www.sammonspreston.com

Simple Parenting (No Recalls)

862-240-1755
www.happykidssmartparents.com

Snugli

800-374-3603 www.snugli.com

Booster Seats

Snugli Booster models beginning "308" made 12/13/11 - 3/3/14. **Problem:** Harness buckle may become stuck in latched position making it difficult to remove child. **Order** replacement buckle on-line www.buckle.evenflo.com or **call:** 800-490-7591

Summer Infant (No Recalls)

800-268-6237 www.summerinfant.com

Sunshine Kids (See Diono)

Teutonia USA (No Recalls)

877-838-8664, www.teutoniausa.com

Tomy International (No Recalls)

800-704-8697 www.tomy.com

Infant Seat

Learning Curve models I420 (with fabric codes ARD, FUI and MAR) made 5/7/06 - 5/15/06. **Problem:** Shell may crack in crash if metal slide on end of crotch strap is not installed correctly. Assure metal slides lie flat against shell in correct location. **Call:** 800-704-8697 for assistance.

Uppababy (No Recalls)

781-413-3000 www.uppababy.com

Urbini (See Aria Child)

Volvo (No Recalls)

800-458-1552 www.volvocars.com