

TV without grading of PACP 7.0 inspection

100 to 101
Downstream inspection

PSR 100 TO 101		PO number	Status CI	Date 01/24/2019	Time 12:23:18 PM	Weather Dry - No precipi...	
Street ROUTE 3		City BROOKLYN ILLINOIS		Owner MESD			
Customer	Operator Blake Zurliene	Certificate number u114-06019815		L surv (ft) 491.500	Total I (ft) 498.000		
Location code Easement/Right of ...	Location details	H (i) 70	W (i)	Shape Circular	Material RCP	Pre-cleaning N	Date cleaned
Upstream MH 100	U R to I (ft) 13.500	U G to I (ft)	U R to G (ft)	Downstream MH 101	DR to I (ft) 13.700	D G to I (ft)	DR to G (ft)
Direction Downstream	Flow control Not Controlled	Drainage area	Lining method	Pjl (ft)	Year constr...	Year renewed	
Video 100 TO 101_1_1242019.mpg		Media label	Additional info			Purpose A	Sheet 1

Dist (ft)	Code	CD	Observation	At		V1	V2	%	St	O&M	Jt	Remarks	Img
<Start inspection>													
0.0	AMH		Manhole									100	
0.0	MM		Miscellaneous Water Level					40.000					X
14.1	SRC		Surface Damage Reinforce...	12	12				5				X
24.0	IR		Infiltration Runner	3	4					4			X
32.8	IR		Infiltration Runner	8	4					4			X
36.3	IR		Infiltration Runner	3	4					4			X
58.0	IR		Infiltration Runner	3	4					4			X
73.7	IR		Infiltration Runner	2	3					4			X
88.1	IR		Infiltration Runner	3	4					4			X
103.8	IR		Infiltration Runner	8	9					4			X
122.6	IR	S01	Infiltration Runner	8	9					4			X
150.7	IR	F01	Infiltration Runner	8	9					4			X
171.9	IR		Infiltration Runner	9	10					4			X
180.0	ID		Infiltration Dipper	4						3			X
211.2	IG		Infiltration Gusher	5						5			X
216.3	IR		Infiltration Runner	3						4			X
225.3	IG		Infiltration Gusher	8						5			X
241.9	IR		Infiltration Runner	3						4			X
255.2	IR		Infiltration Runner	10						4			X
260.9	ID		Infiltration Dipper	3						3			X
266.1	IR	S02	Infiltration Runner	3						4			X
287.0	IR	F02	Infiltration Runner	4						4			X
297.9	ID		Infiltration Dipper	1						3			X
307.7	IR		Infiltration Runner	10						4			X
310.0	IR		Infiltration Runner	4						4			X
328.0	IR		Infiltration Runner	3						4			X

100 to 101

Downstream inspection

[illegible]

100 to 99
Upstream inspection

[illegible]

Downstream inspection

Dist (ft)	Code	CD	Observation	At		V1	V2	%	St	O&M	Jt	Remarks	Img
<Start inspection>													
0.0	AMH		Manhole									56	
0.0	MML		Miscellaneous Water Level					40.000					
6.2	MSA		Miscellaneous Survey Aban...										X
17.1	TFC		Tap Factory Capped	11		12.000							X
<Complete Inspection>													

Downstream inspection

[illegible]

Downstream inspection

Dist (ft)	Code	CD	Observation	At		V1	V2	%	St	O&M	Jt	Remarks	Img
<Start inspection>													
0.0	AMH		Manhole									64	
0.0	MML		Miscellaneous Water Level					35.000					X
30.2	IR		Infiltration Runner	2						4			X
219.6	AMH		Manhole									66	X
<Complete Inspection>													

75 to 74
Upstream inspection

[illegible]

76 to 75
Upstream inspection

Dist (ft)	Code	CD	Observation	At		V1	V2	%	St	O&M	Jt	Remarks	Img
<Start inspection>													
0.0	AMH		Manhole									76	
0.0	MML		Miscellaneous Water Level					35.000					X
367.3	DAR		Deposits Attached Ragging	11	1			5.000		2			X
372.7	AMH		Manhole									75	X
<Complete Inspection>													

Downstream inspection

Dist (ft)	Code	CD	Observation	At		V1	V2	%	St	O&M	Jt	Remarks	Img
<Start inspection>													
0.0	AMH		Manhole									84	
0.0	MML		Miscellaneous Water Level					40.000					X
261.1	DAE		Deposits Attached Encrusta...	12	6			5.000		2			X
602.2	AMH		Manhole									85	X
<Complete Inspection>													

Downstream inspection

[illegible]

TV without grading of PACP 7.0 inspection

99 to 100

Downstream inspection

PSR 99 TO 100		PO number 19018MO-1	Status CI	Date 01/28/2019	Time 10:51:45 AM	Weather Dry - No precipi...	
Street ROUTE 3		City BROOKLYN ILLINOIS		Owner MESD			
Customer	Operator Blake Zurliene	Certificate number u114-06019815		L surv (ft) 998.500	Total I (ft) 1900.000		
Location code Easement/Right of ...	Location details	H (i) 75	W (i) 75	Shape Square	Material RCP	Pre-cleaning N	Date cleaned
Upstream MH 99	U R to I (ft) 13.500	U G to I (ft)	U R to G (ft)	Downstream MH 100	DR to I (ft) 13.500	D G to I (ft)	DR to G (ft)
Direction Downstream	Flow control Not Controlled	Drainage area	Lining method	Pjl (ft)	Year constr...	Year renewed	
Video 99 TO 100_2_1282019.mpg		Media label	Additional info			Purpose A	Sheet 1

Dist (ft)	Code	CD	Observation	At	V1	V2	%	St	O&M	Jt	Remarks	Img
<Start inspection>												
0.0	AMH		Manhole								99	
0.0	MM		Miscellaneous Water Level				50.000					X
461.1	TFA		Tap Factory Activity	12	12.000							X
487.7	TFA		Tap Factory Activity	12	12.000							X
492.6	TFC		Tap Factory Capped	9	18.000							X
493.6	OBI		Obstruction Intruding Thr...	8			5.000		5			X
625.6	TFA		Tap Factory Activity	9	12.000							X
651.9	TFA		Tap Factory Activity	9	12.000							X
794.7	TFA		Tap Factory Activity	12	12.000							X
998.5	AMH		Manhole								CABLE	X
<Complete Inspection>												

Downstream inspection

PSR MH inspection			PO number 19018MO-1		Status CI		Date 01/24/2019		Time 12:36:58 PM		Weather	
Street Forest BLVD			City Granite City IL				Owner MESD					
Customer			Operator David Jones		Certificate number U-114-06019812			L surv (ft) 10.500		Total I (ft)		
Location code Railway		Location details mh near RR tracks.. For...		H (i) 18	W (i)	Shape Circular	Material VCP	Pre-cleaning N	Date cleaned		Pipe use SS	
Upstream MH mh 18		UR to I (ft) 10.700	U G to I (ft)	U R to G (ft)	Downstream MH mh 17		DR to I (ft) 10.000	D G to I (ft)	DR to G (ft)			
Direction Downstream		Flow control	Drainage area	Lining method	Pjl (ft)	Year constr...	Year renewed					
Video MH inspection_357_01_24_2019.mpg				Media label media label		Additional info				Purpose A	Sheet 1	

Dist (ft)	Code	CD	Observation	At		V1	V2	%	St	O&M	Jt	Remarks	Img
<Start inspection>													
0.0	AMH		Manhole									Starting manhole: m h 18.. MH INSPECTI ON ONLY	X
0.0	MML		Miscellaneous Water Level					100.000					X
7.4	MGP		Miscellaneous General Pho...										X
7.4	MGP		Miscellaneous General Pho...										X
10.5	MGP		Miscellaneous General Pho...										X
10.5	AMH		Manhole									Finishing manhole: mh 18.. mh inspecti on/pics	X
<Complete Inspection>													

TV without grading of PACP 7.0 inspection

mh 17 to mh 16

Downstream inspection

PSR MH inspection				PO number 19018MO-1		Status CI		Date 01/24/2019		Time 1:33:44 PM		Weather	
Street Forest BLVD				City Granite City				Owner MESD					
Customer			Operator David Jones		Certificate number U-114-06019812			L surv (ft) 9.600		Total I (ft)			
Location code Railway		Location details Forest BLVD. ROW.. MH...		H (i) 18	W (i)	Shape Circular	Material VCP	Pre-cleaning N	Date cleaned		Pipe use SS		
Upstream MH mh 17		UR to I (ft) 10.000	UG to I (ft)	UR to G (ft)		Downstream MH mh 16	DR to I (ft) 9.600		DG to I (ft)		DR to G (ft)		
Direction Downstream		Flow control	Drainage area	Lining method		PjI (ft)	Year constr...	Year renewed					
Video MH inspection_358_01_24_2019.mpg				Media label media label		Additional info				Purpose A		Sheet 1	

[illegible]