

2023 GUARD RAIL

131 XWAY

SOUTH BOUND BEFORE REST AREA WEST SIDE

1 TRI RAIL

131 XWAY

SOUTH BOUND AT 12 MILE

1 TRI RIB

9 PLASTIC BLOCKS

131 X WAY

SOUTH BOUND AT JEFFERSON RD

2 B CRASH RAILS

1 B RAIL

1 WOODEN POST

1 WOODEN BLOCK

2 STEEL POSTS

1 PLASTIC TRI BLOCK

1 PLASTIC B BLOCK

1 TRI RAIL TO B RAIL TRANSITION RAIL

1 TRI RAIL

131 XWAY

NORTH BOUND AT 13 MILE WEST SIDE

4 B RAIL

2 STEEL POSTS

2 PLASTIC BLOCKS

M20

M20 AT 172ND NORTH SIDE

1 CRASH END AND HARDWARE (BOLTS AND CABLES)

1 CRASH RAIL

1 POST

M20

M20 WEST OF 157TH (4 WAY STOP)

2 B RAIL

2 CRASH RAIL

5 WOOD POSTS

6 WOOD BLOCKS

1 BOTTOM BRACE

1 CRASH END AND HARDWARE

M20

M20 SOUTH OF MECOSTA EAST SIDE OF BRIDGE NORTH END

1 B CRASH RAIL

1 B RAIL

M20 SOUTH OF MECOSTA WEST SIDE OF NORTH BRIDGE

2 B RAIL

1 PLASTIC BLOCK

M20

EAST OF ADDRESS 6387 SOUTH SIDE 2 B RAIL

M20

EAST OF ADDRESS 6387 SOUTH SIDE

2 BRAIL

M20

WEST OF REMUS OIL SOUTH SIDE

2 B RAIL

1 WOOD BLOCK AT CRASH END

PULL POSTS BACK

M66

SOUTH OF 5 MILE EAST SIDE SOUTH END OF RAIL

1 B RAIL

1 WOOD BLOCK (GOES 5 SECTION UP)

M66

SOUTH OF 4 MILE NORTH END PIECE WEST SIDE

1 B RAIL

M66

SOUTH OF 4 MILE EAST SIDE

1 WOOD POST

2 SECTIONS ARE LOOSE NEEDS BOLTS

M66

SOUTH OF JASKSON EAST SIDE

1 B RAIL

M66

NORTH OF MONROE EAST SIDE

1 WOOD BLOCK

2 B RAIL

M66

NORTH OF 10574 ADDRESS WEST SIDE

1 WOODEN POST

3 WOOD BLOCKS MISSING OR BROKE

M66

NORTH OF ARTHUR SOUTH OF 14300 ADDRESS WEST SIDE

1 B RAIL

CRASH END NEEDS ATTACHED NORTH END

M66

SOUTH OF 22510 ADDRESS WEST SIDE

3 B RAIL

1 CURVED B RAIL

OLD STATE RD OVER 131XWAY

SOUTH SIDE

2 B RAIL

2 PLASTIC BLOCKS

PULL 5 POSTS BACK STRAIGHT